

# **HILLCREST MANOR**

## **DECEMBER 2023**

### December 6, 2023

Technician onsite visually inspect the water system and ensure proper functionality of all equipment and components, including both wells and pumps. He checked and cleaned the chlorine container on both wells 01 and 02. He read and recorded the meters at well 01 (371,821,000) and well 02 (146,298,000). He double checked the system for leaks, and everything was in proper working order before his departure.

Time: 2 Hours

#### **December 12, 2023**

Technician onsite visually inspect the water system and ensure proper functionality of all equipment and components, including both wells and pumps. He checked and cleaned the chlorine container on both wells 01 and 02. He double checked the system for leaks, and everything was in proper working order before his departure. Lastly, he removed trash and debris in the well yard before departing.

Time: 2 Hours

#### December 19, 2023

Technician onsite visually inspect the water system and ensure proper functionality of all equipment and components, including both wells and pumps. He checked the chlorinator and added white oil to the dripper on both wells 01 and 02. He read and recorded the meters at well 01 (372,230,000) and well 02 (146,298,000).

Time: 2 Hours

#### **December 26, 2023**

Technician onsite visually inspect the water system and ensure proper functionality of all equipment and components, including both wells and pumps. He checked the chlorinator on both well yards and added white oil to the dripper at wells 01 and 02. He read and recorded the meters at well 01 (372,342,000) and well 02 (146,298,000).

Time: 2 Hours