Utility Services Inc.

Monthly Maintenance Report

Hillcrest Manor Water Users Association

February 2020

February 7, 2020:

Luis onsite to check both wells and visually inspect the system. He filled the chlorinator and oil drippers on both wells. Technician sprayed weed control and cut grass around fire hydrants on Sheila and Madre Mesa

Time: 2 Hours

February 14, 2020:

Tech onsite to check both wells and visually inspect the system. He filled the chlorinator and oil dripper. Sprayed weed control and cut grass around fire hydrant on Alfred. On Sheila technician also scraping old paint off fire hydrant and repainting.

Time: 2 Hours

February 21, 2020:

Tech onsite to check both wells and visually inspect the system for proper functionality. Filled oil drippers on both wells. Technician also scraping old paint off of fire hydrants and repainting on Madre Mesa and Alfred.

Time: 2 Hours

February 28, 2020:

Tech onsite to check both wells and visually inspect the system for proper functionality. He filled the oil drippers on both wells and added bleach to the chlorinator. Technician Flushed and switched Wells. Set Well 2 as primary and Well 1 as back up.

Time: 2 Hours